

LADYBUG LAZY KATE

ASSEMBLY INSTRUCTIONS

LADYBUG LAZY KATE ASSEMBLY INSTRUCTIONS


PARTS

3—1" steel studs (A)
6—hex coupler nut (B)
4—bobbin shafts (C)
2—nylon bolts (D)
4—pulleys (E)
4—tension O rings (F)
4—retainer rings (G)

TOOLS

2—3/8" wrenches or
1—3/8" wrench &
1—pliers

Bobbins are not included.



STEP 1: INSTALL THE HEX COUPLER NUTS


- Slide a steel stud into a front leg holes that it extends evenly on each side of the leg (figure 1).



- Hold one side of the stud and screw on a hex coupler nut on the other side until it touches the leg.
- Hold onto this hex nut and pull it slightly forward to prevent the stud from turning while you screw a hex coupler nut onto the other side of the stud.
- Tighten both nuts by hand up against the leg (figure 2).



- Using two 3/8" wrenches (or a wrench and a pair of pliers), hold one nut with the wrench and tighten the other nut with a wrench about a quarter turn until very snug (figure 3).
- Repeat for the other two holes.




STEP 2: INSTALL THE O-RINGS PULLEYS

- Slide two pulleys onto a nylon bolt and screw it into one side of the center hex coupler nuts (figure 4).
- Repeat for the other side.



STEP 3: INSTALL THE BOBBIN SHAFTS

- Screw a bobbin shaft into each of the remaining hex coupler nuts, two above and two below (figure 5).



STEP 4: INSTALL THE KATE O-RINGS

- Place a tension o-ring onto each pulley (figure 6).
- Push the retainer rings onto the end of each bobbin shaft.



STEP 5: INSTALLING THE BOBBINS

- Remove the retainer rings from the bobbin shafts.
- Slide the bobbins onto the bobbin shafts with the large ends towards the leg.
- Place a tension o-ring on one of the pulleys and over the groove in the bobbin
- Secure the bobbins in place by sliding the retainer rings onto the ends of the bobbin shafts (figure 7).



SPINNING ACCESSORIES

Optional Whorls

high



slow



Niddy Noddy
(maple or cherry)



Spinning Wheel Oil
Bottle



Dizzy Yarn Gauge



Find out more at schachtspindle.com
Schacht Spindle Company
6101 Ben Place Boulder, CO 80301
p. 303.442.3212 800.228.2553 f. 303.447.9273

© 2012 Schacht Spindle Company, Inc. 06.12